



ИНСТРУКЦИЯ ПО СБОРКЕ СТЕЛЛАЖА WS-02



TETCHAIR



КОМПЛЕКТНОСТЬ




① 1PC



② 1PC



③ 1PC







④ 1PC



⑤ 2PC




⑥ 2PC



A 6x50mm  16PCS	B M6x15mm  12PCS	C 4mm  20PCS	D  1PCS
---	--	--	--




TETCHAIR




①



A	6x50mm	C	4mm
			
16PCS		1PCS	

②



B	M6x15mm	C	4mm	D	
					
5PCS		1PCS		1PCS	

P-03

