



ИНСТРУКЦИЯ ПО СБОРКЕ СТОЛА WD-15




TETCHAIR



КОМПЛЕКТНОСТЬ



① 1PC



② 1PC



③ 1PC



④ 1PC



⑤ 2PC



⑥ 4PC



⑦ 1PC



⑧ 1PC



⑨ 3PC



⑩ 1PC




⑪ 1PC










⑫ 1PC



⑬ 2PC




⑭ 2PC



<p>A M6x40mm</p>  <p>20PCS</p>	<p>B M6x30mm</p>  <p>12PCS</p>	<p>C M6x15mm</p>  <p>5PCS</p>	<p>D 4mm</p>  <p>1PCS</p>	<p>E</p>  <p>6PCS</p>	<p>F</p>  <p>1PCS</p>
<p>G $\phi 22 \times M6 \times 15 \text{mm}$</p>  <p>2PCS</p>					




TETCHAIR



①



A	M6x40mm	D	4mm
			
16PCS		1PCS	

②




A	M6x40mm	D	4mm
			
4PCS		1PCS	



P-03




TETCHAIR






③



B	M6x30mm	D	4mm
			
	12PCS		1PCS

④





A	M6x15mm	D	4mm	E		F		G	φ22xM6x15mm
									
	5PCS		1PCS		6PCS		1PCS		2PCS

P-04

3



TETCHAIR



P-05