


BUNNY



X

A=	x1	H=Castor x5
B=	x 1	I=Screw(M6X20mm) x8
C=	x2	J= (M6X30mm) x6
D=	x1	K= (M6X35mm) x2
E=	x1	L= (M6X18mm) x8
F=	- x1	M= - x1
G=	x 1	